Index No. N 19

CASS COUNTY LAND CORNER RECORD

T. 143 R. 28 M. 5TH Coordinates: X _____ Y _____

N1/4 23 Corner common to sections 14, 23



O = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1873

Original monument Post

Original Evidence Found

Year of search _____ By _____

Monument found _____

Bearing Trees

Species	Tam	Tam		
Diameter	8"	10"		
Bearing	N2CE	542E		
Distance	12 Lks	28 Lks		

Original Bearing Trees Found

Species				
Diameter				
Bearing				
Distance				

Subsequent Corner Restoration

Year surveyed 1959 By Co Hwy Dept

Location filed Co Rd #8 SP 11-615-01 BK 2

Monument Squared cedar post

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species				
Diameter				
Bearing				
Distance				

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____ By _____

Filed at _____ Date _____