

Index No. \_\_\_\_\_

CASS COUNTY LAND CORNER RECORD

T. \_\_\_\_\_ R. \_\_\_\_\_ M. \_\_\_\_\_ Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_

Corner common to sections \_\_\_\_\_



= Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed \_\_\_\_\_  
Original monument \_\_\_\_\_

Original Evidence Found

Year of search \_\_\_\_\_ by \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Original Bearing Trees Found

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed:  
Monument:

Evidence of Subsequent Corner Restoration

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Location filed:  
Monument:

Bearing Trees, Reference Objects

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Bearing Trees, Reference Objects

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_


Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed:  
Monument:

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Location filed:  
Monument:

T. 143 R. 28 M. 5TH Coordinates: X Y  
NE 24 Corner common to sections 13, 24 AND 18, 19-143-27



O = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1873  
Original monument Post

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Species	Bearing Trees		Species	
	Fir	Sugar Maple		Fir
Diameter	<u>5"</u>	<u>8"</u>	<u>5"</u>	<u>8"</u>
Bearing	<u>N52E</u>	<u>S42E</u>	<u>S15E</u>	<u>N87E</u>
Distance	<u>10 LKS</u>	<u>10 LKS</u>	<u>8 LKS</u>	<u>3 LKS</u>

Original Bearing Trees Found

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed ? By Geo. Ralph  
 Location filed County Survey Record Book "B" P. 94-95  
 Monument Fnd Old Post  
1920 County Resurvey "E-7" E.B. Horst I.M.  
1920, Ben Clark, Book "C" P. 392 Fnd Corner.  
1923, Greene, Book "D" P. 119 Fnd I.M.

Evidence of Subsequent Corner Restoration

Year of search 1925 By Co Hwy Dept  
State Road #4  
Found Corner

→ also on microfilm - roll 115 BK 2 P. 32

Bearing Trees, Reference Objects

Species	Basswood	Basswood	Balsam	Birch
Diameter	<u>10"</u>	<u>8"</u>	<u>4"</u>	<u>12"</u>
Bearing	<u>N81-30W</u>	<u>S43W</u>	<u>S34-30E</u>	<u>N44-30E</u>
Distance	<u>56.4'</u>	<u>49'</u>	<u>48'</u>	<u>44.8'</u>

Geo. Ralph ties

Bearing Trees, Reference Objects

Birch	Fir	Basswood	
Diameter	<u>12"</u>	<u>8"</u>	
Bearing	<u>N44-30 E</u>	<u>SE</u>	<u>SW</u>
Distance	<u>44.8'</u>	<u>39.7'</u>	<u>49.0'</u>

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
 Location filed \_\_\_\_\_  
 Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
1986 Certificate - Water Cure  
Doc. # 291481  
Found 2 1/2" capped iron pipe 6" below  
surface of old road.  
Set 2" x 24" galvanized iron pipe monument  
with brass cap 8" below road surface.  
18" Spruce N16W 88.45';  
5" W. Oak S82W 89.63';  
18" W. Oak N73E 95.44';  
10" W. Oak S24E 70.57'.

July 1917, Twp rd order shows no survey

Remonumentation certificate prepared \_\_\_\_\_

By \_\_\_\_\_

Filed at \_\_\_\_\_

Date \_\_\_\_\_