


Index No. R17

CASS COUNTY LAND CORNER RECORD

T. 143 R. 28 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
NE 27 Corner common to sections 22, 23, 26, 27



EXISTING SURVEYS

Original Government Survey

Year surveyed 1873  
Original monument Post

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees

Species	<u>Tam</u>	<u>Tam</u>	<u>Tam</u>	<u>Spruce</u>
Diameter	<u>5"</u>	<u>4"</u>	<u>4"</u>	<u>4"</u>
Bearing	<u>N47E</u>	<u>S59E</u>	<u>N46W</u>	<u>S71W</u>
Distance	<u>11 LKS</u>	<u>12 LKS</u>	<u>47 LKS</u>	<u>15 LKS</u>

Original Bearing Trees Found

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1928 By 620  
 Location filed Sec. of State  
 Monument Found all 4 org B.T. remains. Set  
2 x 36" 1/2" w/ brass cap 7143N R28W  
522 | 523  
527 | 526

Evidence of Subsequent Corner Restoration

Year of search \_\_\_\_\_ By \_\_\_\_\_

Bearing Trees, Reference Objects 1928

Species	<u>Dead tam</u>	<u>Tam post</u>
Diameter	<u>4"</u>	<u>3x3" x 6' High</u>
Bearing	<u>S87E</u>	<u>alongside</u>
Distance	<u>73 LKS</u>	<u>iron</u>

Bearing Trees, Reference Objects

_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_

Remonumentation certificate prepared \_\_\_\_\_

By \_\_\_\_\_

Filed at \_\_\_\_\_

Date \_\_\_\_\_