


Index No. T 13-14

CASS COUNTY LAND CORNER RECORD

T. 143 R. 28 M. 5TH Coordinates: X _____ Y _____

5th on Corner common to sections _____

E-W 1/4 line on E. Shore Loch Lake



EXISTING SURVEYS

Original Government Survey

Year surveyed 1928

Original monument 1x36" I.P. w/brass cap 5mc c/a 7 1928

Bearing Trees

Species Cedar Post _____
 Diameter 3x3" x 6' high _____
 Bearing along side _____
 Distance iron _____

Original Evidence Found

Year of search _____ By _____

Monument found _____

Original Bearing Trees Found

Species _____
 Diameter _____
 Bearing _____
 Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

Bearing Trees, Reference Objects

Species _____
 Diameter _____
 Bearing _____
 Distance _____

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Re monumentation certificate prepared _____ By _____

Filed at _____ Date _____