


Index No. T 15-16

CASS COUNTY LAND CORNER RECORD

T. 143 R. 28 M. 5TH Coordinates: X _____ Y _____

SML ON Corner common to sections 27

E-W 1/4 Line left bank of Bay River



EXISTING SURVEYS

Original Government Survey

Year surveyed 1928
 Original monument 1x36" I.P. w/ brass cap 5/27 SML
1928

Original Evidence Found

Year of search _____ By _____
 Monument found _____

Bearing Trees

Species Cedar Post
 Diameter 3x3" x 6'
 Bearing 4 long side
 Distance iron

Original Bearing Trees Found

Species _____
 Diameter _____
 Bearing _____
 Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
 Location filed _____
 Monument _____

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species _____
 Diameter _____
 Bearing _____
 Distance _____

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Year surveyed _____ By _____
 Location filed _____
 Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Re monumentation certificate prepared _____ By _____
 Filed at _____ Date _____