


Index No. V 13-14

CASS COUNTY LAND CORNER RECORD

T. 143 R. 28 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
MC # 4 Corner common to sections 27, 34



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1873  
Original monument Post

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees

Species	<u>Tum</u>	<u>Tum</u>	_____	_____
Diameter	<u>6"</u>	<u>5"</u>	_____	_____
Bearing	<u>N87E</u>	<u>S88E</u>	_____	_____
Distance	<u>550 LKS</u>	<u>610 LKS</u>	_____	_____

Original Bearing Trees Found

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1928 By GLO  
 Location filed Sec. of State  
 Monument Record distance Falls in lake - Set 1x36"  
1/2" brass cap MC 1527  
534  
1928

Evidence of Subsequent Corner Restoration

Year of search \_\_\_\_\_ By \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_

Bearing Trees, Reference Objects

Species Set tum post 3x3" x 6' High alongside iron  
 Diameter \_\_\_\_\_  
 Bearing \_\_\_\_\_  
 Distance \_\_\_\_\_

Bearing Trees, Reference Objects

\_\_\_\_\_

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
 Location filed \_\_\_\_\_  
 Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_

Remonumentation certificate prepared \_\_\_\_\_ By \_\_\_\_\_  
 Filed at \_\_\_\_\_ Date \_\_\_\_\_