


Index No. V 23

CASS COUNTY LAND CORNER RECORD

T. 143 R. 28 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
N<sup>14</sup> 36 Corner common to sections 25, 36



EXISTING SURVEYS

Original Government Survey  
 Year surveyed 1873  
 Original monument Post

Original Evidence Found  
 Year of search \_\_\_\_\_ By \_\_\_\_\_  
 Monument found \_\_\_\_\_

Bearing Trees  
 Species Cedar Cedar  
 Diameter 10" 10"  
 Bearing S55E N32W  
 Distance 13LKS 15LKS

Original Bearing Trees Found  
 Species \_\_\_\_\_  
 Diameter \_\_\_\_\_  
 Bearing \_\_\_\_\_  
 Distance \_\_\_\_\_

Subsequent Corner Restoration  
 Year surveyed 1920 By GLO  
 Location filed Sec. of State  
 Monument Found path orig B.T.S (SE B.T DOWN)  
Set 1 x 36" 1/4" w/ brass cap 1/4 S35  
536  
1920

Evidence of Subsequent Corner Restoration  
 Year of search 1959 By Co Hwy Dept  
Co RD 8 SP11-615-01 BR2  
1.P. in place (GLO) 2362.9' E. of Fred

Bearing Trees, Reference Objects  
 Species Cedar  
 Diameter 6"  
 Bearing N50E  
 Distance 10LKS

Bearing Trees, Reference Objects  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_

Subsequent Corner Restoration  
 Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
 Location filed \_\_\_\_\_  
 Monument \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found  
 Year of search \_\_\_\_\_ By \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_

Remonumentation certificate prepared \_\_\_\_\_  
 Filed at \_\_\_\_\_

By \_\_\_\_\_  
 Date \_\_\_\_\_