


Index No. W-X 24

CASS COUNTY LAND CORNER RECORD

T. 143 R. 2B M. 5th Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_

SMC ON Corner common to sections 36


E 1/4 LINE



EXISTING SURVEYS

Original Government Survey

Year surveyed 1920  
Original monument 1x36" IR w/brass cap



Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees

|          |                   |                   |       |       |
|----------|-------------------|-------------------|-------|-------|
| Species  | <u>Tam</u>        | <u>Tam</u>        | _____ | _____ |
| Diameter | <u>6"</u>         | <u>4"</u>         | _____ | _____ |
| Bearing  | <u>S 18 1/2 W</u> | <u>N 81 1/4 W</u> | _____ | _____ |
| Distance | <u>64 LKS</u>     | <u>72 LKS</u>     | _____ | _____ |

Original Bearing Trees Found

|          |       |       |       |       |
|----------|-------|-------|-------|-------|
| Species  | _____ | _____ | _____ | _____ |
| Diameter | _____ | _____ | _____ | _____ |
| Bearing  | _____ | _____ | _____ | _____ |
| Distance | _____ | _____ | _____ | _____ |

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration

Year of search \_\_\_\_\_ By \_\_\_\_\_

Bearing Trees, Reference Objects

|          |       |       |       |       |
|----------|-------|-------|-------|-------|
| Species  | _____ | _____ | _____ | _____ |
| Diameter | _____ | _____ | _____ | _____ |
| Bearing  | _____ | _____ | _____ | _____ |
| Distance | _____ | _____ | _____ | _____ |

Bearing Trees, Reference Objects

|          |       |       |       |       |
|----------|-------|-------|-------|-------|
| Species  | _____ | _____ | _____ | _____ |
| Diameter | _____ | _____ | _____ | _____ |
| Bearing  | _____ | _____ | _____ | _____ |
| Distance | _____ | _____ | _____ | _____ |

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_

Remonumentation certificate prepared \_\_\_\_\_ By \_\_\_\_\_

Filed at \_\_\_\_\_ Date \_\_\_\_\_