


Index No. A3

CASS COUNTY LAND CORNER RECORD

T. 143 R. 29 M. 5TH Coordinates: X _____ Y _____
N1/4 6 Corner common to sections 6 AND 31-144-29



O = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1873
Original monument Post

Original Evidence Found

Year of search _____ By _____
Monument found _____

	Bearing	Trees
Species	<u>Cedar</u>	<u>Cedar</u>
Diameter	<u>4"</u>	<u>4"</u>
Bearing	<u>N54E</u>	<u>S57W</u>
Distance	<u>13 LKS</u>	<u>9 LKS</u>

	Bearing	Trees	Found
Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1924 By GLO
Location filed Sec. of State
Monument Set 1x36" 1/2" in brass cap proportionally
1/4 531
56
1924

Evidence of Subsequent Corner Restoration

Year of search 1965 By William Okerman
Found GLO monument in good condition;
5" Spruce N34°30'W 22.44' now 8";
Tamarack S28E 31.68' now 7".

Bearing Trees, Reference Objects

Species	<u>Spruce</u>	<u>Tam</u>
Diameter	<u>5"</u>	<u>6"</u>
Bearing	<u>N34-30W</u>	<u>S28-45E</u>
Distance	<u>34LKS</u>	<u>48LKS</u>

Bearing Trees, Reference Objects

Tamarack	<u>Spruce</u>
<u>9"</u>	<u>6"</u>
<u>N56E</u>	<u>S37E</u>
<u>4.7'</u>	<u>5.2'</u>

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
CERTIFICATE - BILL OKERMAN - 1965

Remonumentation certificate prepared _____

By _____

Filed at _____

Date _____