


Index No. JR3

CASS COUNTY LAND CORNER RECORD

T. 143 R. 29 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
N1/4 13 Corner common to sections 12, 13



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1873  
Original monument Post

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

	Bearing	Trees	
Species	<u>Poplar</u>	<u>Birch</u>	
Diameter	<u>8"</u>	<u>5"</u>	
Bearing	<u>S12W</u>	<u>N22E</u>	
Distance	<u>16 LKS</u>	<u>9 LKS</u>	

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1918 By GLC  
Location filed Sec of State  
Monument Set 1436" 1/4" w/ brass cap 1/4 512  
513  
1918

Evidence of Subsequent Corner Restoration

Year of search \_\_\_\_\_ By \_\_\_\_\_

	Bearing	Trees, Reference Objects	
Species	<u>Maple</u>	<u>Maple</u>	
Diameter	<u>26"</u>	<u>10"</u>	
Bearing	<u>S28-45E</u>	<u>N52W</u>	
Distance	<u>25 LKS</u>	<u>65 LKS</u>	

Bearing Trees, Reference Objects

_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_

Remonumentation certificate prepared \_\_\_\_\_ By \_\_\_\_\_  
Filed at \_\_\_\_\_ Date \_\_\_\_\_