


Index No. K 22

CASS COUNTY LAND CORNER RECORD

T. 143 R. 29 M. 5TH Coordinates: X _____ Y _____
NW 1/16 Corner common to sections 13



EXISTING SURVEYS

Original Government Survey

Year surveyed 1918
Original monument 1X36" 1/16" w/ Brass NW 1/16 513
CYP 1918

Original Evidence Found

Year of search _____ By _____
Monument found _____

Species		Bearing		Trees	
<u>Cedar</u>	<u>14"</u>	<u>N51°42'W</u>	<u>27LKS</u>	<u>Cedar</u>	<u>12"</u>

Species		Bearing		Trees Found	
_____	_____	_____	_____	_____	_____
_____	_____	_____	_____	_____	_____
_____	_____	_____	_____	_____	_____
_____	_____	_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species _____	_____	_____	_____
Diameter _____	_____	_____	_____
Bearing _____	_____	_____	_____
Distance _____	_____	_____	_____

Bearing Trees, Reference Objects

_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Re monumentation certificate prepared _____ By _____
Filed at _____ Date _____