


Index No. LR1

CASS COUNTY LAND CORNER RECORD

T. 143 R. 29 M. 5TH Coordinates: X _____ Y _____
E14 14 Corner common to sections 13, 14



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1873
Original monument lost

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species Tum Tum _____
Diameter 4" 4" _____
Bearing N37E N19 1/2 W _____
Distance 47 LKS 64 LKS _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed 1918 By GLD
Location filed Sec. of State
Monument Set 1x36" lip w/ brass cap 1/4
514/513
1918

Evidence of Subsequent Corner Restoration

Year of search 4/23/86 By Freeman-Humitzsch
End 1/2" iron in intersection roads E-W-N.

Bearing Trees, Reference Objects

Species Oak Ash _____
Diameter 8" 6" _____
Bearing N37E N69-45W _____
Distance 136 LKS 90 LKS _____

Bearing Trees, Reference Objects

L-21

Subsequent Corner Restoration

Year surveyed 3/2001 By CCSO
Location filed file # 2001.014
Monument Found 1 1/2" OD IP, down 0.2',
4 1/2 N. of & CR # 136, on & Five Mile Pt.
Rd. Witnessed as follows.

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

16" Maple N29° E 108.11' *
P. Pole S41° E, 56.51' *
P. Pole S73° W, 133.04' *
*distance to double head nail

Remonumentation certificate prepared A000667032

Filed at _____

By _____

Date _____