


Index No. N 25

CASS COUNTY LAND CORNER RECORD

T. 143 R. 29 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
NE 24 Corner common to sections 13, 24 AND 18, 19-143-28



EXISTING SURVEYS

Original Government Survey

Year surveyed 1873  
Original monument Post

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Species	Bearing Trees			
	Tam.	Tam.	Tam.	Tam.
Diameter	<u>5"</u>	<u>7"</u>	<u>6"</u>	<u>5"</u>
Bearing	<u>N20W</u>	<u>S60W</u>	<u>N70E</u>	<u>S20E</u>
Distance	<u>16 LKS</u>	<u>22 LKS</u>	<u>12 LKS</u>	<u>30 LKS</u>

Original Bearing Trees Found

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

○ = Corner

Subsequent Corner Restoration

Year surveyed 1918 By GLO  
Location filed Sec. of State  
Monument Set 2x36" I.P. w/ brass cap T143N  
S13 / S18  
S24 / S19  
R29W / R28W

Evidence of Subsequent Corner Restoration

Year of search 1974 By Co. Hwy Dept  
(Co. RD # 73  
Found 2" I.M.

4/23/86 - Freeman - Hummitzsch - End 2" I.M.  
w/ brass cap. nt edge of Swamp.

Bearing Trees, Reference Objects

Species	Bearing Trees, Reference Objects			
	1918	1918	1918	1918
Diameter	<u>5"</u>	<u>5"</u>	<u>5"</u>	<u>6"</u>
Bearing	<u>N27 1/4 E</u>	<u>N17 1/4 W</u>	<u>S52 1/4 W</u>	<u>S8 E</u>
Distance	<u>57 LKS</u>	<u>116 LKS</u>	<u>198 LKS</u>	<u>186 LKS</u>

Bearing Trees, Reference Objects

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_

Remonumentation certificate prepared \_\_\_\_\_

By \_\_\_\_\_

Filed at \_\_\_\_\_

Date \_\_\_\_\_