


Index No. Q 25

CASS COUNTY LAND CORNER RECORD

T. 143 R. 29 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
S1116 Corner common to sections 24 and 19-143-28



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1918  
Original monument 1x36" 1/2" pin/brass cap S1116 S24/S19 1918

Bearing Trees

Species Balsam Maple  
Diameter 12" 12"  
Bearing S78 1/2 E N18 W  
Distance 10.65 39.65  
Black Birch 14" on line 10.36 CH. SOUTH

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Original Bearing Trees Found

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Bearing Trees, Reference Objects

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Evidence of Subsequent Corner Restoration

Year of search \_\_\_\_\_ By \_\_\_\_\_

Bearing Trees, Reference Objects

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_

Remonumentation certificate prepared \_\_\_\_\_ By \_\_\_\_\_  
Filed at \_\_\_\_\_ Date \_\_\_\_\_