


Index No. R 18-19

CASS COUNTY LAND CORNER RECORD

T. 143 R. 29 M. 5TH Coordinates: X _____ Y _____
MC# 5 Corner common to sections 23, 26



EXISTING SURVEYS

Original Government Survey

Year surveyed 1873
Original monument lost

Species	Bearing	Trees	Distance
<u>Sugar</u>	<u>Sugar</u>		
<u>8"</u>	<u>8"</u>		
<u>S41E</u>	<u>N53 1/2 E</u>		
<u>9 LKS</u>	<u>14 LKS</u>		

Original Evidence Found

Year of search _____ By _____
Monument found _____

Original Bearing Trees Found

Species	Bearing	Distance
_____	_____	_____
_____	_____	_____
_____	_____	_____
_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1918 By GLO
Location filed Sec. of State
Monument At orig. dist. Set 1x36" 1/4" brass cap
7143N R29W
MC 523
526
1921

Bearing Trees, Reference Objects

Species	Bearing	Distance
<u>Basswood</u>	<u>Maple</u>	
<u>5"</u>	<u>6"</u>	
<u>S36 1/2 E</u>	<u>N50W</u>	
<u>42 LKS</u>	<u>42 LKS</u>	

Evidence of Subsequent Corner Restoration

Year of search 1974 By BLM
Find 1" iron w/ cap set in 1921 - no B.T.S LEFT

Bearing Trees, Reference Objects

Species	Bearing	Distance
<u>Basswood</u>	<u>Maple</u>	
<u>12"</u>	<u>14"</u>	
<u>S17W</u>	<u>S77W</u>	
<u>62 1/2 LKS</u>	<u>74 LKS</u>	

R-18, 19

Subsequent Corner Restoration

Year surveyed 1974 By Co. Hwy Dept
Location filed Co. Rd # 73
Monument Found US 610 corner 57.42' W of
1/4 corner

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared A000667033

Filed at _____

By _____

Date _____