


Index No. R19

CASS COUNTY LAND CORNER RECORD

T. 143 R. 29 M. 5TH Coordinates: X _____ Y _____
N 14 26 Corner common to sections 23, 26



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1873
Original monument Post

Original Evidence Found

Year of search _____ By _____
Monument found _____

	Bearing Trees	
Species	<u>Sugar Maple</u>	<u>Ironwood</u>
Diameter	<u>14"</u>	<u>6"</u>
Bearing	<u>N32W</u>	<u>S47E</u>
Distance	<u>845</u>	<u>2365</u>

Original Bearing Trees Found	
Species	_____
Diameter	_____
Bearing	_____
Distance	_____

Subsequent Corner Restoration

Year surveyed 1918 By GLO
Location filed Sec. of State
Monument Set 1x36" 1/8" w Brass cap 1/4 523
526
1918

Evidence of Subsequent Corner Restoration

Year of search 1974 By Co. Hwy Dept.
Co Rd # 73
Found 2" 1. M. in place 17.72' w and 33'
N. of P.L. roads.

Bearing Trees, Reference Objects

Species	<u>Maple</u>	<u>Maple</u>
Diameter	<u>14"</u>	<u>6"</u>
Bearing	<u>S59W</u>	<u>N72 1/2 W</u>
Distance	<u>3965</u>	<u>6765</u>

Bearing Trees, Reference Objects

R-19

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
PLAT - SUGAR POINT
R.F. SCHNEIDER 1973

CERT OF SUR. SHOWS MON FOUND
MAR 2002 Pa Schaberg

Jan. 2004 D. Warner # 42656
CERT. OF SUR. SHOWS MON FOUND

Remonumentation certificate prepared A000667034

Filed at _____ By _____ Date _____