


Index No. 521

CASS COUNTY LAND CORNER RECORD

T. 143 R. 29 M. 5TH Coordinates: X _____ Y _____
N 1/16 Corner common to sections 25, 26



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1918
Original monument 1x36" i.p. w/ brass cap 1918

Original Evidence Found

Year of search _____ By _____
Monument found _____

| Bearing Trees | |
|---------------------------|---------------|
| Species <u>Poplar</u> | <u>Birch</u> |
| Diameter <u>6"</u> | <u>4"</u> |
| Bearing <u>N 72 1/4 E</u> | <u>N 80 W</u> |
| Distance <u>26 LKS</u> | <u>7 LKS</u> |

Original Bearing Trees Found

| | | | |
|----------|-------|-------|-------|
| Species | _____ | _____ | _____ |
| Diameter | _____ | _____ | _____ |
| Bearing | _____ | _____ | _____ |
| Distance | _____ | _____ | _____ |

Subsequent Corner Restoration

Year surveyed 1974 By BLM
Location filed Sec. of State
Monument Found NW 1918 B.T. - new 7" and post with cap

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

| | | | |
|----------------------------|-------|-------|-------|
| Species <u>Pine</u> | _____ | _____ | _____ |
| Diameter <u>6"</u> | _____ | _____ | _____ |
| Bearing <u>S 39 E</u> | _____ | _____ | _____ |
| Distance <u>20 1/2 LKS</u> | _____ | _____ | _____ |

Bearing Trees, Reference Objects

| | | | |
|-------|-------|-------|-------|
| _____ | _____ | _____ | _____ |
| _____ | _____ | _____ | _____ |
| _____ | _____ | _____ | _____ |
| _____ | _____ | _____ | _____ |

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Re monumentation certificate prepared _____ By _____
Filed at _____ Date _____