


Index No. T 23-24

CASS COUNTY LAND CORNER RECORD

T. 143 R. 29 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_

C.C. ON Corner common to sections 25

E-W 1/4 ON Restored meander line



EXISTING SURVEYS

Original Government Survey

Year surveyed 1921 C 525 C  
 Original monument 1x36" 1/4" i.p. w/brass cap C C C  
1921

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
 Monument found \_\_\_\_\_

Bearing Trees

Species Maple Ironwood \_\_\_\_\_  
 Diameter 20" 10" \_\_\_\_\_  
 Bearing N20W S55-30W \_\_\_\_\_  
 Distance 34cks 88cks \_\_\_\_\_

Original Bearing Trees Found

Species \_\_\_\_\_  
 Diameter \_\_\_\_\_  
 Bearing \_\_\_\_\_  
 Distance \_\_\_\_\_

Subsequent Corner Restoration

Year surveyed 1974 By BLM  
 Location filed Sec. of State  
 Monument End 1" i.p. w/brass cap and 1921 B.T.  
Burned maple stump N20W 34cks

Evidence of Subsequent Corner Restoration

Year of search \_\_\_\_\_ By \_\_\_\_\_

Bearing Trees, Reference Objects

Species \_\_\_\_\_  
 Diameter \_\_\_\_\_  
 Bearing \_\_\_\_\_  
 Distance \_\_\_\_\_

Bearing Trees, Reference Objects

\_\_\_\_\_

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
 Location filed \_\_\_\_\_  
 Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_

Remonumentation certificate prepared \_\_\_\_\_

By \_\_\_\_\_

Filed at \_\_\_\_\_

Date \_\_\_\_\_