


Index No. U21

CASS COUNTY LAND CORNER RECORD

T. 143 R. 29 M. 57H Coordinates: X _____ Y _____
S116 Corner common to sections 25, 26



EXISTING SURVEYS

Original Government Survey

Year surveyed 1918
Original monument 1x36" 1/2 P.W. / Dress 5116
cup 1918

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species Elm Ash
Diameter 10" 7"
Bearing S58 1/2 E S3W
Distance 326 LKS 827 LKS

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed 1974 By BLM
Location filed Sec. of State
Monument NO EVIDENCE OF 1918 SURVEY

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____