



T. 143 R. 29 M. 5th Coordinates: X _____ Y _____
N 1/4 36 Corner common to sections 25, 36

EXISTING SURVEYS

Original Government Survey		Original Evidence Found	
Year surveyed <u>9/1918, A.L. Kimmell, Cad. Engr.</u>	<u>1/4 S 25</u>	Year of search <u>1974</u> by <u>BLM</u>	
Original monument <u>Set 1"x 36" I.P. w/brass cap</u>	<u>S 36</u>	Monument found <u>Iron Pipe</u>	
<u>MN Historical Society, notes page 23</u>	<u>1918</u>	<u>MN Hist. Society, notes page 7</u>	

Bearing Trees	
Species <u>Elm</u>	<u>Elm</u>
Diameter <u>8"</u>	<u>7"</u>
Bearing <u>S 4°45' E</u>	<u>S 43 1/2° W</u>
Distance <u>43 links</u>	<u>15 links</u>

Original Bearing Trees Found	
Species <u>Elm</u>	
Diameter <u>17"</u>	
Bearing <u>S 4°45' E</u>	
Distance <u>43 links</u>	

Subsequent Corner Restoration

Year surveyed 7/1974 By C.E. Akin, Jr., Surveyor, BLM
 Location filed: MN Historical Society, notes page 7
 Monument: Found 1"x 36" I.P. with brass cap up 6", at 22.45 chains(1481.70') from the closing corner for the 1/4 line of sec. 25, found 1918 iron post, firmly set, 5 links (3.30'), E. of graveled road, 25 links(16.50 feet) wide and Kimmell's 1918 witness.

Bearing Trees, Reference Objects	
Species _____	_____
Diameter _____	_____
Bearing _____	_____
Distance _____	_____

Evidence of Subsequent Corner Restoration

Year of search 1960 By BIA
 Location filed: Project No. 132-25
 Monument: Brass cap in place on centerline and witnesses as follows.

Bearing Trees, Reference Objects	
Species <u>Elm</u>	<u>Basswood</u>
Diameter <u>36"</u>	<u>14"</u>
Bearing <u>SE</u>	<u>SW</u>
Distance <u>64.0'</u>	<u>64.0'</u>

Subsequent Corner Restoration

Year surveyed 1980 By R.A. Mustonen, LS 11946
 Location filed: Certificate of Survey, #769
 Monument: Indicates a monument found

 5/1985, T.L. Freeman, CCHD/SO & C.R. Krause, USFS CCHD/SO Field Book 1, image 69 & USFS Field Bk 1, pg 21 Found GLO iron, with brass cap, bent, straighten and field check angles and distances N. and E., 18.4' E. of centerline Co. Rd. #136, in E. ditch, on fence line E. Reset iron flush and surround with rock ring and witnesses as follows.
 17" Elm, S 4°45' E, 28.38'(1918)
 6" N. Pine, S 43° W, 90.22'
 Alum Cap RM, S 60° E, 25.20'

 12/1999, T.L. Freeman, LS 21367
 Plat of BATTLE POINT ESTATES, Doc. #420335
 Indicates brass capped monument found.

 6/2019, CCHD/SO #2019.002
 Found 2" ODIP with GLO brass cap, down 0.2', 18'+/-, E. of centerline Co. Rd. #136, in ditch and witnesses as follows.
 8" Red Pine, S 43° W, 90.22'(1985) 60d spike, flush, E. side
 Alum Cap RM, S 60° E, 24.82'(1985) leans due to large rock
 8" Ash, N 30 E, 75.25' duplex nail, up 1.0', W. side
 Power Pole, N 39 W, 68.68' duplex nail, up 1.0', E. side

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
 Location filed: _____
 Monument: _____

