


Index No. A 13

CASS COUNTY LAND CORNER RECORD

T. 143 R. 30 M. 5TH Coordinates: X _____ Y _____
NE 4 Corner common to sections 3, 4 AND 33, 34 - 144-30



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1875
Original monument Post

Original Evidence Found

Year of search _____ By _____
Monument found _____

Species	Bearing Trees			
	Balsam	Balsam	Balsam	Ironwood
Diameter	<u>6"</u>	<u>6"</u>	<u>6"</u>	<u>6"</u>
Bearing	<u>S24W</u>	<u>N30W</u>	<u>N10E</u>	<u>S55E</u>
Distance	<u>12 LKS</u>	<u>9 LKS</u>	<u>25 LKS</u>	<u>24 LKS</u>

Original Bearing Trees Found

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1921 By GLO
Location filed Sec of State
Monument AT Proportions 1 dist - set 2x36" 1/4" w/ brass cy
T114N R30W
S33 | S34
S4 | S3

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Species	Bearing Trees, Reference Objects			
	Birch	Poplar	Poplar	Poplar
Diameter	<u>4"</u>	<u>6"</u>	<u>5"</u>	<u>5"</u>
Bearing	<u>N60-45E</u>	<u>S5-15E</u>	<u>S48-15W</u>	<u>N71-15W</u>
Distance	<u>49 LKS</u>	<u>51 LKS</u>	<u>38 LKS</u>	<u>38 LKS</u>

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____