


Index No. A 24-25

CASS COUNTY LAND CORNER RECORD

T. 143 R. 30 M. 5TH Coordinates: X _____ Y _____
MC# 11 Corner common to sections 1 AND 36-144-30



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed _____
Original monument _____

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species _____
Diameter _____
Bearing _____
Distance _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed 1924 By GLD
Location filed Sec. of State
Monument Set 1x36" lip. w/ brass cap 7144N
mc / 536 R30W
51
7143N
1924

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species Maple Maple
Diameter 6" 6"
Bearing N53-45E S66-30E
Distance 33 LKS 36 LKS

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
PLAT - HEDIN HARBOR ON LEECH LAKE
L. E. LANE 1960

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____