


Index No. A 25

CASS COUNTY LAND CORNER RECORD

T. 143 R. 30 M. 5TH Coordinates: X _____ Y _____
NE 1 Corner common to sections 1 AND 6-143-29 AND 31-144-29
AND 36-144-30



EXISTING SURVEYS

Original Government Survey

Year surveyed _____

Original monument _____

Bearing Trees

Species _____

Diameter _____

Bearing _____

Distance _____

Original Evidence Found

Year of search _____ By _____

Monument found _____

Original Bearing Trees Found

Species _____

Diameter _____

Bearing _____

Distance _____

Subsequent Corner Restoration

Year surveyed 1907 By JOHN CURO

Location filed COUNTY SURVEY RECORD BOOK A' P 252-253

Monument FIND OLD CORNER B.T.S.: 20" CEDAR N41E 7.3', 18" CEDAR N43W 9.2', FIR S24W 7.9', 10" FIR S8E 5.9'
FIND POINT OF OLD STAKE SET PINE POST

Evidence of Subsequent Corner Restoration

Year of search 1924 By GLO

FIND wood Stake & NE & NW B.T.S. SET 2x36" 1/2" w/ brass cap

T 144 N

| | |
|---------------|---------------|
| <u>R 30 W</u> | <u>R 29 W</u> |
| <u>536</u> | <u>531</u> |
| <u>57</u> | <u>56</u> |

Bearing Trees, Reference Objects

Species _____

Diameter _____

Bearing _____

Distance _____

Bearing Trees, Reference Objects

| | | | |
|---------------|----------------|----------------|---------------------|
| <u>Cedar</u> | <u>Ash</u> | <u>Cedar</u> | <u>20" N.W. BT.</u> |
| <u>10"</u> | <u>8"</u> | <u>14"</u> | <u>Cedar</u> |
| <u>N12E</u> | <u>S79-30W</u> | <u>S13-15E</u> | <u>N43W</u> |
| <u>20 LKS</u> | <u>25 LKS</u> | <u>133 LKS</u> | <u>14 LKS</u> |

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

PLAT - HEDIN HARBOR ON LEECH LAKE

L. E. LANE 1960

PLAT - HEDIN HARBOR ON LEECH LAKE, FIRST ADDITION

PETER J. MEYER 1970

Remonumentation certificate prepared _____ By _____

Filed at _____ Date _____