


Index No. C 9

CASS COUNTY LAND CORNER RECORD

T. 143 R. 30 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
E14 5 Corner common to sections 4,5



EXISTING SURVEYS

Original Government Survey

Year surveyed 1875  
Original monument Post

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees	
Species <u>Tam</u>	<u>Tam</u>
Diameter <u>8"</u>	<u>8"</u>
Bearing <u>S44E</u>	<u>N38W</u>
Distance <u>15 LKS</u>	<u>23 LKS</u>

Original Bearing Trees Found

Species _____	_____
Diameter _____	_____
Bearing _____	_____
Distance _____	_____

Subsequent Corner Restoration

Year surveyed 1921 By GLO  
Location filed Sec. of State  
Monument End wood Stake - and both BITS - badly decayed - set 1x36" l.f. with brass cap  
114  
55/54  
1921

Evidence of Subsequent Corner Restoration

Year of search \_\_\_\_\_ By \_\_\_\_\_

Bearing Trees, Reference Objects

Species <u>Tam</u>	<u>Tam</u>
Diameter <u>8"</u>	<u>10"</u>
Bearing <u>N46-45E</u>	<u>S83W</u>
Distance <u>53 LKS</u>	<u>62 LKS</u>

Bearing Trees, Reference Objects

_____	_____
_____	_____
_____	_____
_____	_____

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_

Remonumentation certificate prepared \_\_\_\_\_

By \_\_\_\_\_

Filed at \_\_\_\_\_

Date \_\_\_\_\_