


Index No. 62

CASS COUNTY LAND CORNER RECORD

T. 143 R. 30 M. 57H Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
C.W. 116 Corner common to sections 7



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1920  
Original monument 1x3/8" I.P. w/ brass cap w/116 c  
57 c

Bearing Trees	
Species <u>Poplar</u>	<u>Poplar</u>
Diameter <u>10"</u>	<u>76"</u>
Bearing <u>N79-15W</u>	<u>S47 1/2 E</u>
Distance <u>5 LKS</u>	<u>14 LKS</u>

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Original Bearing Trees Found

Species _____	_____	_____	_____
Diameter _____	_____	_____	_____
Bearing _____	_____	_____	_____
Distance _____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1983 By Walter Curo  
Location filed \_\_\_\_\_  
Monument Found 1" iron pipe with brass cap.

Evidence of Subsequent Corner Restoration

Year of search \_\_\_\_\_ By \_\_\_\_\_

Bearing Trees, Reference Objects

Species <u>W. Oak</u>	<u>W. Oak</u>	<u>W. Oak</u>
Diameter <u>7"</u>	<u>10"</u>	<u>12"</u>
Bearing <u>S64W</u>	<u>N50W</u>	<u>N40E</u>
Distance <u>60.60'</u>	<u>46.70'</u>	<u>24.41'</u>

Bearing Trees, Reference Objects

_____	_____	_____
_____	_____	_____
_____	_____	_____
_____	_____	_____

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_

Certificate - Walt Curo - 1983  
Doc. # 268851

Remonumentation certificate prepared \_\_\_\_\_

By \_\_\_\_\_

Filed at \_\_\_\_\_

Date \_\_\_\_\_