


Index No. H2

CASS COUNTY LAND CORNER RECORD

T. 143 R. 30 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
SW 1/16 Corner common to sections 7



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1921  
Original monument 1x36" 1IP.w/brass cap SW 1/16 S7 1921

Bearing Trees	
Species <u>Birch</u>	<u>Birch</u>
Diameter <u>8"</u>	<u>5"</u>
Bearing <u>N68 1/2 E</u>	<u>S64 1/2 W</u>
Distance <u>37 LKS</u>	<u>41 LKS</u>

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Original Bearing Trees Found

Species _____	_____	_____	_____
Diameter _____	_____	_____	_____
Bearing _____	_____	_____	_____
Distance _____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1983 By Walter Curo  
Location filed \_\_\_\_\_  
Monument Found 1" iron pipe with brass cap.

Bearing Trees, Reference Objects		
Species <u>W. Oak</u>	<u>W. Oak</u>	<u>W. Oak</u>
Diameter <u>6"</u>	<u>8"</u>	<u>7"</u>
Bearing <u>S82 W</u>	<u>N4 E</u>	<u>S73 E</u>
Distance <u>12.42'</u>	<u>49.88'</u>	<u>54.06'</u>

Evidence of Subsequent Corner Restoration

Year of search \_\_\_\_\_ By \_\_\_\_\_

Bearing Trees, Reference Objects

_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_

Cert. Ficate - walt Curo - 1983  
Doc. # 268852

Remonumentation certificate prepared \_\_\_\_\_ By \_\_\_\_\_  
Filed at \_\_\_\_\_ Date \_\_\_\_\_