


Index No. H3

CASS COUNTY LAND CORNER RECORD

T. 143 R. 30 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
C.S. 116 Corner common to sections 7



EXISTING SURVEYS

Original Government Survey

Year surveyed 1920  
Original monument 1x36" I.P. w/ brass cap <sup>C</sup> 5 1/61 57 <sup>C</sup>  
1920

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees  
Species Poplar R. Oak \_\_\_\_\_  
Diameter 10" 22" \_\_\_\_\_  
Bearing N7E N46 1/2 W \_\_\_\_\_  
Distance 7 LKS 37 LKS \_\_\_\_\_

Original Bearing Trees Found

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Subsequent Corner Restoration

Year surveyed 1983 By Walter Curo  
Location filed \_\_\_\_\_  
Monument Found 1" iron pipe with brass cap.

Evidence of Subsequent Corner Restoration

Year of search \_\_\_\_\_ By \_\_\_\_\_

Bearing Trees, Reference Objects  
Species W. Oak W. Oak W. Oak  
Diameter 8" 9" 8"  
Bearing N48W N82E S4E  
Distance 35.82' 31.27' 35.51'

Bearing Trees, Reference Objects

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_

Certificate - Walter Curo - 1983  
Doc. # 268843

Re monumentation certificate prepared \_\_\_\_\_ By \_\_\_\_\_

Filed at \_\_\_\_\_ Date \_\_\_\_\_