


Index No. J 20-21

CASS COUNTY LAND CORNER RECORD

T. 143 R. 30 M. 5TH Coordinates: X _____ Y _____
MC # 3 Corner common to sections 11, 14



EXISTING SURVEYS

Original Government Survey

Year surveyed 1875
Original monument Post

Original Evidence Found

Year of search _____ By _____
Monument found _____

Species	Bearing	Trees
<u>Elm</u>	<u>4"</u>	<u>Elm</u>
<u>Elm</u>	<u>12"</u>	<u>Elm</u>
<u>N11E</u>	<u>67LKS</u>	<u>S68W</u>
<u>Elm</u>	<u>540LKS</u>	

Original Bearing Trees Found

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

○ = Corner

Subsequent Corner Restoration

Year surveyed 1924 By GLO
Location filed Sec. of State
Monument Find SW Pt. Set w/ MC N36° 11' P w/ brass cap

Evidence of Subsequent Corner Restoration

Year of search 1989 By David Landecker
Found GLO monument in good condition

Species	Bearing	Trees	Reference Objects
<u>Elm</u>	<u>7"</u>	<u>Elm</u>	<u>514</u>
<u>Elm</u>	<u>12"</u>	<u>Elm</u>	<u>R30W</u>
<u>N33W</u>	<u>225LKS</u>	<u>S11-15W</u>	<u>1924</u>
<u>Elm</u>	<u>298LKS</u>		

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
<u>Maple</u>	<u>8"</u>	<u>N80W</u>	<u>38.72'</u>
<u>Maple</u>	<u>7"</u>	<u>S16W</u>	<u>28.74'</u>
<u>Maple</u>	<u>6"</u>	<u>N22W</u>	<u>60.90'</u>
<u>Dead Elm</u>	<u>24"</u>	<u>S11W</u>	<u>196.7'</u>

(1924 BT)

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
Plot - Lakewood Shores - R.F. Schneider - 1974
1989 Certificate - David Landecker
Doc. # 317230

Remonumentation certificate prepared _____

By _____

Filed at _____

Date _____