


Index No. M1-2

CASS COUNTY LAND CORNER RECORD

T. 143 R. 30 M. 5TH Coordinates: X _____ Y _____

AP# 1 TR Corner common to sections _____

229, AP# 2 TR 375



EXISTING SURVEYS

Original Government Survey

Year surveyed 1919 TR 358
 Original monument 1x36" 1/2" iron pipe with brass cap AP1 TR 229 AP2 TR 375
1919

Bearing Trees

Species _____
 Diameter _____
 Bearing _____
 Distance _____

Original Evidence Found

Year of search _____ By _____
 Monument found _____

Original Bearing Trees Found

Species _____
 Diameter _____
 Bearing _____
 Distance _____

Subsequent Corner Restoration

Year surveyed 1983 By Walter Curo
 Location filed _____
 Monument found 1" iron pipe with brass cap.

Bearing Trees, Reference Objects

Species	<u>W. Oak</u>	<u>W. Oak</u>	<u>W. Oak</u>
Diameter	<u>9"</u>	<u>7"</u>	<u>7"</u>
Bearing	<u>S42W</u>	<u>S8W</u>	<u>N48E</u>
Distance	<u>19.20'</u>	<u>22.30'</u>	<u>14.10'</u>

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Year surveyed _____ By _____
 Location filed _____
 Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
Certificate - Walt Curo - 1983
Doc. # 268847

Remonumentation certificate prepared _____

By _____

Filed at _____

Date _____