


T. 143 R. 30 M. 5TH Coordinates: X _____ Y _____

SMC on Corner common to sections 18

S 1/4 Line



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1919
 Original monument 1x36" IP w/ brass cap S 518 / SMC 1919

| Bearing Trees | |
|------------------------|----------------|
| Species <u>Bl. Ash</u> | <u>Bl. Ash</u> |
| Diameter <u>7"</u> | <u>8"</u> |
| Bearing <u>N67.45W</u> | <u>S55-15W</u> |
| Distance <u>10 LKS</u> | <u>10 LKS</u> |

Original Evidence Found

Year of search _____ By _____
 Monument found _____

Original Bearing Trees Found

| | |
|----------------|-------|
| Species _____ | _____ |
| Diameter _____ | _____ |
| Bearing _____ | _____ |
| Distance _____ | _____ |

Subsequent Corner Restoration

Year surveyed 1983 By Walter Curo
 Location filed _____
 Monument Set 2" x 5' iron pipe with brass cap.

Bearing Trees, Reference Objects

| Bearing Trees, Reference Objects | | |
|----------------------------------|---------------|--------------|
| Species <u>Asn</u> | <u>Ash</u> | <u>Maple</u> |
| Diameter <u>9"</u> | <u>12"</u> | <u>10"</u> |
| Bearing <u>N14W</u> | <u>S46E</u> | <u>N62E</u> |
| Distance <u>35.74'</u> | <u>25.00'</u> | <u>8.91'</u> |

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

| | |
|-------|-------|
| _____ | _____ |
| _____ | _____ |
| _____ | _____ |
| _____ | _____ |

Subsequent Corner Restoration

Year surveyed _____ By _____
 Location filed _____
 Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
Certificate - Walt Curo - 1983
Doc. # 268849