


Index No. A 13

CASS COUNTY LAND CORNER RECORD

T. 143 R. 31 M. 5TH Coordinates: X _____ Y _____
NE 4 Corner common to sections 3, 4 AND 33, 34 - 144-31



EXISTING SURVEYS

Original Government Survey

Year surveyed 1875
Original monument Post

Species	Bearing		Trees	
	Tam	Dead Tam	Dead Tam	Dead Tam
Diameter	<u>4"</u>	<u>4"</u>	<u>5"</u>	<u>5"</u>
Bearing	<u>N59E</u>	<u>S69E</u>	<u>N63W</u>	<u>S30W</u>
Distance	<u>67 LKS</u>	<u>90 LKS</u>	<u>9 LKS</u>	<u>30 LKS</u>

Original Evidence Found

Year of search _____ By _____
Monument found _____

Original Bearing Trees Found

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

O = Corner

Subsequent Corner Restoration

Year surveyed 1919 By GLO
Location filed Sec. of State
Monument End 2x2 cedar stake & all 4 dead goat B.T.S
Set 2x36" lip. w/ brass cap
7144N
R 31W
533/534
54/53

Bearing Trees, Reference Objects

Species	Dead Tam	Dead Tam	Dead Tam	Dead Tam
Diameter	<u>3"</u>	<u>3"</u>	<u>3"</u>	<u>3"</u>
Bearing	<u>N46 1/2 E</u>	<u>S83E</u>	<u>S78W</u>	<u>N38 1/2 W</u>
Distance	<u>8 LKS</u>	<u>48 LKS</u>	<u>58 LKS</u>	<u>126 LKS</u>

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Re-monumentation certificate prepared _____ By _____
Filed at _____ Date _____