


T. 143 R. 31 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
NE1 Corner common to sections 1 AND 6-143-30 AND 31-144-30  
AND 36-144-31



EXISTING SURVEYS

Original Government Survey

Year surveyed 1875  
Original monument Post

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Species	Bearing	Trees	Distance
<u>Tam</u>	<u>Cedar</u>	<u>Cedar</u>	<u>Cedar</u>
<u>8"</u>	<u>6"</u>	<u>10"</u>	<u>6"</u>
<u>S46E</u>	<u>S42W</u>	<u>N3E</u>	<u>N3W</u>
<u>27 LKS</u>	<u>44 LKS</u>	<u>5.30 CH.</u>	<u>4.70 CH.</u>

Original Bearing Trees Found

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1920 By GLC  
Location filed Sec. of State  
Monument Found old wood stake 6 or 8 BRS. T144N  
14" Cedar N3E 518 LKS, 14" Dead Tam S46E 266 LKS S36 | S31  
and 12" Cedar N3W 466 LKS R31W 51 | S6 R30W  
Set 3x36" i.p. w/ brass cap T143N 1920

Evidence of Subsequent Corner Restoration

Year of search \_\_\_\_\_ By \_\_\_\_\_

Species	Bearing	Trees, Reference Objects	Distance
<u>Cedar</u>	<u>Cedar</u>	<u>Cedar</u>	
<u>4"</u>	<u>4"</u>	<u>14"</u>	
<u>S30E</u>	<u>S49W</u>	<u>N3W</u>	
<u>25 LKS</u>	<u>27 LKS</u>	<u>466 LKS</u>	

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_