

Index No. C5

CASS COUNTY LAND CORNER RECORD

T. 143 R. 31 M. 57H Coordinates: X 576 Y 376
 Corner common to sections 376

EXISTING SURVEYS

Original Government Survey

Year surveyed 1675
 Original monument lost
 Species Cedar
 Diameter 8"
 Bearing tan
 Distance 11 LKS

Subsequent Corner Restoration

Year surveyed 1919
 By G. L. C.
 Location filed Sec 8 State
 Monument found with 16' x 17' SET
 114
1X36" 11 R. m brass cap
 Species Cedar
 Diameter 10"
 Bearing N 75 3/4 W
 Distance 11 LKS

Original Evidence Found

Year of search _____
 By _____
 Monument found _____

Original Bearing Trees Found


Species _____
 Diameter _____
 Bearing _____
 Distance _____

Evidence of Subsequent Corner Restoration

Year of search _____
 By _____

Bearing Trees, Reference Objects

Year of search _____
 By _____



Subsequent Corner Restoration

Year surveyed _____ By _____
 Location filed _____
 Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
Nov. 2004 T. Freeman #21367
Cert. of Survey shows brass mon. found

Re monumentation certificate prepared _____ By _____
 Filed at _____ Date _____