

Index No. C9

### CASS COUNTY LAND CORNER RECORD

T. 143 R. 31 M. 57H Coordinates: X 4/5 Y \_\_\_\_\_  
Corner common to sections \_\_\_\_\_

#### EXISTING SURVEYS

Original Evidence Found \_\_\_\_\_  
Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Original Bearing Trees Found \_\_\_\_\_

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Evidence of Subsequent Corner Restoration

Year of search \_\_\_\_\_ By \_\_\_\_\_

Bearing Trees, Reference Objects \_\_\_\_\_  
\_\_\_\_\_

Bearing Trees, Reference Objects \_\_\_\_\_  
\_\_\_\_\_

Original Government Survey

Year surveyed 1875  
Original monument lost

Bearing Trees

Species Spruce 4"  
Tan 6"  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Subsequent Corner Restoration

Year surveyed 1919 By Geo

Location filed S.C. of State  
Monument Set 1136" 11/11/1919 cap reportedly

Bearing Trees, Reference Objects \_\_\_\_\_  
Species Head Tan Shub Head Tan Shub  
Diameter 6"  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Bearing Trees, Reference Objects \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing 555E  
Distance N80 1/4 W 241 LKS

#### Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

#### Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_

Re monumentation certificate prepared \_\_\_\_\_

By \_\_\_\_\_

Filed at \_\_\_\_\_

Date \_\_\_\_\_

