


Index No. E 1

CASS COUNTY LAND CORNER RECORD



T. 143 R. 31 M. 5TH Coordinates: X _____ Y _____
NW 7 Corner common to sections 6, 7

EXISTING SURVEYS

Original Government Survey

Year surveyed 1874

Original monument 8" W. Cedar

Species	Bearing	Tree	Distance
<u>Cedar</u>	<u>Tam</u>	<u>Tam</u>	<u>Cedar</u>
<u>8"</u>	<u>9"</u>	<u>12"</u>	<u>12"</u>
<u>N70E</u>	<u>N50W</u>	<u>S30W</u>	<u>S40E</u>
<u>6LKS</u>	<u>4LKS</u>	<u>18LKS</u>	<u>23LKS</u>

Original Evidence Found

Year of search _____ By _____

Monument found _____

Original Bearing Trees Found

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

O = Corner

Subsequent Corner Restoration

Year surveyed 1919 By GLD

Location filed Sec. of State

Monument Set 2x36" 1 1/2" w/ brass cap from R/W stake
Set by State Hwy ENGINEER. 7143N

51 | 56
R32W S12 | S7 R31W

Bearing Trees, Reference Objects 1919

Species	Bearing	Tree	Distance
<u>Cedar</u>	<u>Cedar</u>	<u>Balsam</u>	<u>Cedar</u>
<u>6"</u>	<u>5"</u>	<u>10"</u>	<u>10"</u>
<u>N84 3/4 E</u>	<u>S73 3/4 E</u>	<u>S78 3/4 W</u>	<u>N17W</u>
<u>55LKS</u>	<u>61LKS</u>	<u>224 LKS</u>	<u>224 LKS</u>

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument Nov. 2004 T. Freeman #21367
Let. of Surv. shows mon. found (brass cap)

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____