Index No. E25

CASS COUNTY LAND CORNER RECORD

T. 143 R. 31 M. 5TH Coordinates: X _____ Y _____

NE 12 Corner common to sections 1, 12 AND 6, 7-143-30



O = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1875

Original monument Post

Bearing Trees

Species	Tam	Cedar	Cedar	Cedar
Diameter	12"	8"	12"	4"
Bearing	N41E	58E	S20W	N35W
Distance	24 LKS	44 LKS	43 LKS	45 LKS

Original Evidence Found

Year of search _____ By _____

Monument found _____

Original Bearing Trees Found

Species				
Diameter				
Bearing				
Distance				

Subsequent Corner Restoration

Year surveyed 1919 By GLO

Location filed Sec. of State -

Monument Found all 4 BTS. -(NW Standing)

Set 2 X 36" LIP w/brass cap T143N

R31W R30W

51 | 56

~~32~~ 57 1919

Bearing Trees, Reference Objects

Species	Cedar	Balm Gilead	Cedar	Cedar
Diameter	8"	6"	6"	8"
Bearing	N67¾E	S57½E	S26¼W	N35W
Distance	72 LKS	56 LKS	7 LKS	45 LKS

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Remonumentation certificate prepared _____ By _____ Date _____

Filed at _____

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed

Monument

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____