


Index No. _____

CASS COUNTY LAND CORNER RECORD

T. _____ R. _____ M. _____ Coordinates: X _____ Y _____

Corner common to sections _____



= Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed _____
Original monument _____

Original Evidence Found

Year of search _____ by _____
Monument found _____

Bearing Trees

Species _____
Diameter _____
Bearing _____
Distance _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed:
Monument:

Evidence of Subsequent Corner Restoration

Year of search _____ By _____
Location filed:
Monument:

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed:
Monument:


Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
Location filed:
Monument:

Index No. E 9

CASS COUNTY LAND CORNER RECORD

T. 143 R. 31 M. 57H Coordinates: X NE 8 Y _____
Corner common to sections 4, 5, 8, 9



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1875
Original monument Post

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species	Cedar	Cedar	Tam	Balsam
Diameter	6"	4"	6"	10"
Bearing	N10W	S4W	N66E	East
Distance	45 LKS	37 LKS	220 LKS	282 LKS

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1957 By H. CURD
Location filed COUNTY BOOK "D" P426
Monument FWD F.M.

Evidence of Subsequent Corner Restoration

Year of search 1919 By GLO
Find NW 1/4 NE 8 T. Stumps - Set 2x36" 1/4" w/brass
Cap T143N R31W
also find old wood stake 55/54
SB/59
1919

Bearing Trees, Reference Objects

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Bearing Trees, Reference Objects

N. Pine	N. Pine	Local Corner
10"	10"	
N 87-30 E	S 71-15 E	N 46 W
415 LKS	406 LKS	4 LKS

By _____ Date _____

Remuneration certificate prepared _____ Filed at _____

1935 - Minn. Hwy Dept - old map in Recorder's Office
 Monument found brass cap monument
 Location filed Map's notes in file preliminary plat
 Year surveyed 1976 By DNK-Engineering
2 1/2" iron pipe & brass cap
walker to Cass Lake

Evidence of Subsequent Corner Restoration Found

Subsequent Corner Restoration