Index No. 624 CASS COUNTY LAND	O CORNER RECORD
T. 143 R. 31 M. 574 Coordinates: X C.E. 1/6 Corner common to sections 12	Y
C.E. 1/6 Corner common to sections	
FYICTING	S SURVEYS
Original Government Survey	Original Evidence Found
Vacc surveyed 1919 E 16	Year of search By
Year surveyed 1919 Original monument 1136" Ith wildress 512	Monument found
Cap 1919	Monument found
Damelan Tassa	Original Bearing Trees Found O = Corner
Species Aspen Jiline	Species
Diameter	Diameter
Species Aspen Jiline Diameter 6" 14" Bearing 570'14E NO! 12W	Bearing
Distance 40 LKS 105 LKs	Distance
Subsequent Corner Restoration	Evidence of Subsequent Corner Restoration
Year surveyed 1982 By Walter Curo	Year of searchBy
Monument Found 1"x 3/2" mon Dips with brass	
Cap bent over set a"x5' iron	
pipe with brass cap up 18".	
pipe with blass cap up to.	
Bearing Trees, Reference Objects	Bearing Trees, Reference Objects
Species Poplar Poplar W. Oak	Dedring Trees, Reference Objects
Species Pophr Pophr W. Oak Diameter O" 9" 10"	
Bearing 530W 53QE N55E	
Distance 36.83' 40.20' 87.17'	
Subsequent Corner Restoration Year surveyed By Location filed Monument	Evidence of Subsequent Corner Restoration Found Year of search By Certificate Walt Curo - 1983 Drc. #268840
.,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	
Remonumentation certificate prepared	By
	Date