


T. 143 R. 31 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
 MC # 20 Corner common to sections 11,14



EXISTING SURVEYS

Original Government Survey
Year surveyed <u>1875</u>
Original monument <u>Post</u>

Bearing Trees	
Species <u>W. oak</u>	<u>R. oak</u>
Diameter <u>18"</u>	<u>12"</u>
Bearing <u>N37E</u>	<u>S1W</u>
Distance <u>34LKS</u>	<u>32LKS</u>

Original Evidence Found	
Year of search _____	By _____
Monument found _____	

Original Bearing Trees Found	
Species _____	_____
Diameter _____	_____
Bearing _____	_____
Distance _____	_____

○ = Corner

Subsequent Corner Restoration	
Year surveyed <u>1919</u>	By <u>GLW</u>
Location filed <u>Sec. of State</u>	
Monument <u>End both orig. B.T. Stumps - corner falls below</u> <u>mean highwater mark - set 1x36" lip. T143W R31W</u> <u>w/brass cap 0.25CH. East</u>	
<u>mc / S11</u> <u>S14</u>	

Bearing Trees, Reference Objects	
Species <u>W. oak</u>	<u>R. oak</u>
Diameter <u>5"</u>	<u>16"</u>
Bearing <u>N28E</u>	<u>S26E</u>
Distance <u>12LKS</u>	<u>19LKS</u>

Evidence of Subsequent Corner Restoration	
Year of search _____	By _____

Bearing Trees, Reference Objects	

Subsequent Corner Restoration	
Year surveyed _____	By _____
Location filed _____	
Monument _____	

Evidence of Subsequent Corner Restoration Found	
Year of search _____	By _____