


T. 143 R. 31 M. 5TH Coordinates: X _____ Y _____
5116 Corner common to sections 13 and 18-143-30



EXISTING SURVEYS

Original Government Survey

Year surveyed 1919 5116
Original monument 1x36" ID. w/brass cap 513/518
1919

Bearing Trees

Species W. Oak W. Oak _____
Diameter 4" 12" _____
Bearing S76E N20 1/2 W _____
Distance 25.45 39.45 _____

Original Evidence Found

Year of search _____ By _____
Monument found _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed 1983 By Walter Caro
Location filed _____
Monument Set 2"x36" iron pipe with brass cap flush with ground in power line

Bearing Trees, Reference Objects

Species W. Oak W. Oak W. Pine
Diameter 8" 10" 14"
Bearing N60W N32E S52E
Distance 58.18' 70.47' 51.18'

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
Certificate - Walt Caro - 1983
Doc. # 268841