


Index No. M9

CASS COUNTY LAND CORNER RECORD

T. 143 R. 31 M. 57A Coordinates: X _____ Y _____
S116 Corner common to sections 17,16



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1919
Original monument 1X36" 1/4" W / brass cap S116
S17/S16 1919

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees
Species W. oak W. oak
Diameter 8" 6"
Bearing S69°1/2°E S86°1/4°W
Distance 20245 5545

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed 1976 By DNR-Engineering
Location filed map, notes, preliminary certificate on file
Monument Found brass cap monument bent over.

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____

By _____

Filed at _____

Date _____