


Index No. N 14-15

CASS COUNTY LAND CORNER RECORD

T. 143 R. 31 M. 5TH Coordinates: X _____ Y _____

M C# 34 Corner common to sections B, 22



○ = Corner

EXISTING SURVEYS

Original Government Survey

Original Evidence Found

Year surveyed 1875
Original monument Post

Year of search _____ By _____
Monument found _____

Bearing Trees

Species	<u>Ash</u>	<u>Elm</u>	_____
Diameter	<u>6"</u>	<u>8"</u>	_____
Bearing	<u>S15E</u>	<u>N78W</u>	_____
Distance	<u>11 LKS</u>	<u>39 LKS</u>	_____

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Evidence of Subsequent Corner Restoration

Year surveyed 1919 By GLO
 Location filed Sec. of State
 Monument End SE B.T. Stump & NW B.T. Dead
Set 1436 I.P. willow cap T143N R31W
S151ML
S22
1919

Year of search _____ By _____

Bearing Trees, Reference Objects

Bearing Trees, Reference Objects

Species	<u>W. oak</u>	<u>W. ash</u>	_____
Diameter	<u>14"</u>	<u>8"</u>	_____
Bearing	<u>S57 3/4 W</u>	<u>N58 1/4 W</u>	_____
Distance	<u>138 LKS</u>	<u>274 LKS</u>	_____

_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Evidence of Subsequent Corner Restoration Found

Year surveyed _____ By _____
 Location filed _____
 Monument _____

Year of search _____ By _____
PLAT - KINGS ISLAND PARK
EDWIN RANKIN 1963

Remuneration certificate prepared _____ By _____

Filed at _____ Date _____