


Index No. N 8

CASS COUNTY LAND CORNER RECORD

T. 143 R. 31 M. 5TH Coordinates: X _____ Y _____
E 116 Corner common to sections 17, 20



○ = Corner

EXISTING SURVEYS

Original Government Survey
 Year surveyed 1919
 Original monument 1x36" HP. willow cap 1919 E 116 517 520

Original Evidence Found
 Year of search _____ By _____
 Monument found _____

Bearing Trees
 Species R. oak
 Diameter 5"
 Bearing S 11/2 E
 Distance 273.43

Original Bearing Trees Found
 Species _____
 Diameter _____
 Bearing _____
 Distance _____

Subsequent Corner Restoration
 Year surveyed _____ By _____
 Location filed _____
 Monument _____

Evidence of Subsequent Corner Restoration
 Year of search _____ By _____

Bearing Trees, Reference Objects
 Species _____
 Diameter _____
 Bearing _____
 Distance _____

Bearing Trees, Reference Objects

Subsequent Corner Restoration
 Year surveyed _____ By _____
 Location filed _____
 Monument _____

Evidence of Subsequent Corner Restoration Found
 Year of search _____ By _____

Remonumentation certificate prepared _____ By _____
 Filed at _____ Date _____