


Index No. 019

CASS COUNTY LAND CORNER RECORD

T. 143 R. 31 M. 5TH Coordinates: X _____ Y _____
C.N. 116 Corner common to sections 23



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1919
Original monument 1x36" 1/2 P. w/ brass ^C N 116 1/2 S 23
cup 1919

Original Evidence Found

Year of search _____ By _____
Monument found _____

| Species | | Bearing | | Trees | |
|-----------------|---------------|-------------------|--------------|-------|-------|
| <u>Aspen</u> | <u>4"</u> | <u>R. oak</u> | <u>4"</u> | _____ | _____ |
| <u>56 1/4 E</u> | <u>21 LKS</u> | <u>N 70 1/4 W</u> | <u>8 LKS</u> | _____ | _____ |

Original Bearing Trees Found

| | | | |
|----------|-------|-------|-------|
| Species | _____ | _____ | _____ |
| Diameter | _____ | _____ | _____ |
| Bearing | _____ | _____ | _____ |
| Distance | _____ | _____ | _____ |

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

| | | | |
|----------|-------|-------|-------|
| Species | _____ | _____ | _____ |
| Diameter | _____ | _____ | _____ |
| Bearing | _____ | _____ | _____ |
| Distance | _____ | _____ | _____ |

Bearing Trees, Reference Objects

| | | | |
|-------|-------|-------|-------|
| _____ | _____ | _____ | _____ |
| _____ | _____ | _____ | _____ |
| _____ | _____ | _____ | _____ |
| _____ | _____ | _____ | _____ |

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____