


T. 143 R. 31 M. 5TH Coordinates: X _____ Y _____
NE 30 Corner common to sections 19, 20, 29, 30



EXISTING SURVEYS

Original Government Survey
 Year surveyed 1875
 Original monument Post

Species	Bearing	Tree	Distance
<u>Aspen</u>	<u>Aspen</u>	<u>W. Pine</u>	<u>Aspen</u>
<u>8"</u>	<u>8"</u>	<u>14"</u>	<u>8"</u>
<u>S71E</u>	<u>S49W</u>	<u>N62W</u>	<u>N85E</u>
<u>56 LKS</u>	<u>56 LKS</u>	<u>49 LKS</u>	<u>145 LKS</u>

Original Evidence Found
 Year of search _____ By _____
 Monument found _____

Original Bearing Trees Found

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration
 Year surveyed 1917 By E.P. Hobst
 Location filed County Book 2 P 78
 Monument Fwd Steel Angle Bar Set By W&A From Govt
B.TS: Popple B.T. Still Green - Stump of W. Pine still there

Evidence of Subsequent Corner Restoration
 Year of search 1919 By G.L.D
End SE B.T (now 20") and Stumps of SW & NW
B.TS Set 2x36" l.p. w/ brass cap T143N, R31W
519 | 520
530 | 529
1919

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
<u>Aspen</u>	<u>W. oak</u>	<u>W. oak</u>	<u>W. oak</u>
<u>12"</u>	<u>7"</u>	<u>10'</u>	<u>10'</u>
<u>N80 1/2 E</u>	<u>S60 1/4 E</u>	<u>S2W</u>	<u>N4 1/2 W</u>
<u>180 LKS</u>	<u>38 LKS</u>	<u>106 LKS</u>	<u>51 LKS</u>

Subsequent Corner Restoration
 Year surveyed _____ By _____
 Location filed _____
 Monument June 1919
Trap Road Order shows no survey

Evidence of Subsequent Corner Restoration Found
 Year of search _____ By _____