


Index No. 523

CASS COUNTY LAND CORNER RECORD

T. 143 R. 31 M. 5TH Coordinates: X _____ Y _____
C.N. 116 Corner common to sections 25



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1919
Original monument 1x36" 1P. w/ bases ^C N 116/ 525
cap 1919

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species	<u>R. oak</u>	<u>N. pine</u>	_____	_____
Diameter	<u>8"</u>	<u>12"</u>	_____	_____
Bearing	<u>N 31 1/4 E</u>	<u>S 18 1/2 W</u>	_____	_____
Distance	<u>56 LKS.</u>	<u>22 LKS</u>	_____	_____

Original Bearing Trees Found

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Bearing Trees, Reference Objects

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____