


Index No. X1

CASS COUNTY LAND CORNER RECORD

T. 143 R. 31 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
W14 31 Corner common to sections 31



EXISTING SURVEYS

**Original Government Survey**

Year surveyed 1874  
Original monument Post

**Bearing Trees**

Species	<u>Tam</u>	<u>Tam</u>	_____
Diameter	<u>6"</u>	<u>6"</u>	_____
Bearing	<u>S23E</u>	<u>WEST</u>	_____
Distance	<u>53LKS</u>	<u>75LKS</u>	_____

**Original Evidence Found**

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

**Original Bearing Trees Found**

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

**Subsequent Corner Restoration**

Year surveyed 1919 By GLD  
Location filed Sec of State  
Monument Set 1x36" IP. w/ brass cup pin part way 11y  
11y  
536/531  
1919

**Evidence of Subsequent Corner Restoration**

Year of search \_\_\_\_\_ By \_\_\_\_\_

**Bearing Trees, Reference Objects**

Species	<u>Tam</u>	<u>Tam</u>	<u>local coc.</u>
Diameter	<u>5"</u>	<u>4"</u>	<u>5" oak stake</u>
Bearing	<u>S15 3/4 E</u>	<u>N32 W</u>	<u>7 LK W.</u>
Distance	<u>211 LKS</u>	<u>230 LKS</u>	<u>1 LK N.</u>

**Bearing Trees, Reference Objects**

_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

**Subsequent Corner Restoration**

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

**Evidence of Subsequent Corner Restoration Found**

Year of search \_\_\_\_\_ By \_\_\_\_\_

Remonumentation certificate prepared \_\_\_\_\_ By \_\_\_\_\_  
Filed at \_\_\_\_\_ Date \_\_\_\_\_