


Index No. X-Y 9

CASS COUNTY LAND CORNER RECORD

T. 143 R. 31 M. 5TH Coordinates: X _____ Y _____
M.C.# 6 Corner common to sections 32, 33



○ = Corner

EXISTING SURVEYS

Original Government Survey
 Year surveyed 1875
 Original monument Post

Original Evidence Found
 Year of search _____ By _____
 Monument found _____

Bearing Trees
 Species R. Oak R. Oak
 Diameter 8" 6"
 Bearing S11W S85E
 Distance 51LKS 18LKS

Original Bearing Trees Found
 Species _____
 Diameter _____
 Bearing _____
 Distance _____

Subsequent Corner Restoration
 Year surveyed 1919 By GLO
 Location filed Sec. of State
 Monument End SW Q.T. - Now 24" - Set 1x36" I.P.
W/brass cap
MC
532 | 533
7143N | R31

Evidence of Subsequent Corner Restoration
 Year of search _____ By _____

Bearing Trees, Reference Objects 1919
 Species R. Oak Willow
 Diameter 12" 18"
 Bearing S59 1/2 E S51 3/4 W
 Distance 197 LKS 96 LKS

Bearing Trees, Reference Objects

Subsequent Corner Restoration
 Year surveyed _____ By _____
 Location filed _____
 Monument _____

Evidence of Subsequent Corner Restoration Found
 Year of search _____ By _____
PLAT - LITTLE PONDEROSA
R.F. SCHNEIDER 1967 IRON - NOT LABELED M.C.

Remonumentation certificate prepared _____ By _____
 Filed at _____ Date _____