


Index No. E5

CASS COUNTY LAND CORNER RECORD

T. 144 R. 25 M. 5th Coordinates: X _____ Y _____
NE 7 Corner common to sections 5,6,7,8



EXISTING SURVEYS

Original Government Survey

Year surveyed 1876
Original monument Post

Original Evidence Found

Year of search _____ By _____
Monument found _____

	Bearing	Trees	
Species	<u>Cedar</u>	<u>Maple</u>	<u>Birch</u>
Diameter	<u>6"</u>	<u>8"</u>	<u>8"</u>
Bearing	<u>N68E</u>	<u>S25E</u>	<u>N27W</u>
Distance	<u>10 LKS</u>	<u>28 LKS</u>	<u>10 LKS</u>

Original Bearing Trees Found			
Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Bearing Trees, Reference Objects

_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
Certificate - Jim Parker - 1985
Set obliterated - 2 1/2" i.p. w/ brass cap
8" Ash N28°E 32.29'
8" Maple S50°E 61.72'
3" Tamarack S13°W 29.38'
5" Aspen N25°W 69.61'
Doc. # 2816608

Remonumentation certificate prepared _____

By _____

Filed at _____

Date _____