


Index No. E 7

CASS COUNTY LAND CORNER RECORD

T. 144 R. 25 M. 574 Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
N 1/4 8 Corner common to sections 5, 8



EXISTING SURVEYS

Original Government Survey

Year surveyed 1876  
Original monument Post

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees

Species Tam Tam \_\_\_\_\_  
Diameter 6" 4" \_\_\_\_\_  
Bearing N35E S56W \_\_\_\_\_  
Distance 15 LKS 6 LKS \_\_\_\_\_

Original Bearing Trees Found

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration

Year of search \_\_\_\_\_ By \_\_\_\_\_

Bearing Trees, Reference Objects

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Bearing Trees, Reference Objects

\_\_\_\_\_

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_

Certificate - Jim Parker - 1985  
Set last - 5/8" x 5' aluminum rod w/cap  
3" Spruce N55°E 51.58'  
6" Aspen S55°E 30.79'  
DOC # 281469

Remonumentation certificate prepared \_\_\_\_\_ By \_\_\_\_\_  
Filed at \_\_\_\_\_ Date \_\_\_\_\_